

THE IMPORTANCE OF STRAINER BASKETS



1. WHAT THE DEBRIS LOOKS LIKE



Trash & debris in oily water collection pit.

THE IMPORTANCE OF STRAINER BASKETS



2. THE EFFECTS ON EQUIPMENT WITHOUT A STRAINER



Pump Impeller blocked by debris.



Worn and damaged pump impeller. Caused by debris.



Check valve blocked by oily water debris.



Equipment blockages due to rubbish.

THE IMPORTANCE OF STRAINER BASKETS






3. THE ULTRASPIN STRAINER



Large Ultraspin strainer.

Ultraspin Technology

46 Wadhurst Drive
Boronia, VIC, 3155
Australia

 +61 3 8841 7200 / 1800 467 266 (After Hours)
 +61 3 8841 7299
 sales@ultraspin.com.au

™ Trade Mark of Ultraspin Pty Ltd

www.ultraspin.com.au

THE IMPORTANCE OF STRAINER BASKETS






4. EXAMPLES OF GOOD STRAINERS



UltraSpin strainers in action removing debris.

UltraSpin Technology
46 Wadhurst Drive
Boronia, VIC, 3155
Australia

 +61 3 8841 7200 / 1800 467 266 (After Hours)
 +61 3 8841 7299
 sales@ultraspin.com.au

™ Trade Mark of UltraSpin Pty Ltd
www.ultraspin.com.au