

Case Study

Customer: BHP Billiton – DMO Wolwekrans Main Gate

Requirement: Oil Spill clean-up

Year: 2011



Contact Details:

Procon Environmental
Witbank+27 (0)13 697 4617
Pretoria+27 (0)12 674 9030
procon@pro-enviro.co.za

Procon Environmental Technologies were called to deal with an oil spill clean-up.



Before



Before

Solution

The work consisted of absorbing all free oil, utilizing our absorbent Biozorb, Microbe Soil Treat & Absorbent Rolls.

For the rehabilitation of contaminated soil we used Terrazyme as the bioremediation treatment of choice.

High pressure washer was used along with Bio-Solve to remove stains and any residual pollution.



After

Procon Environmental

www.pro-enviro.co.za

We provide Oily Water Treatment, Floating Skimmers and Vehicle Wash Water Reclaim Systems.

Call us for further information on our Ultraspin innovative hydro cyclone designs, separating oil and other contaminants from water while our Mycelx filtration removes 100% of TPH and oil and grease from water.