

# Case Study

**Customer:** Railway Depot

**Requirement:** Rehabilitation of area after derailment

**Year:** 2015

**Product:** Pro Soil Treat and Terrazyme



**Contact Details:**

Procon Environmental  
Witbank +27 (0)13 697 4617  
Pretoria +27 (0)12 667 5389  
procon@pro-enviro.co.za

Procon Environmental Technologies were requested to remediate an area after a diesel spillage which occurred during a derailment incident.



**Solution**

The contaminated soil was manually dug up to the level of contamination, microbial products, Pro Soil Treat and Terrazyme where then mixed into the contaminated soil.

The soil was placed in heaps and then further treated with nutrients. The soil was then sprayed with water to start the remediation process.

The heaps of soil where then levelled and the area inspected to the clients satisfaction. Before and after sample analyses were taken and the area was reported free of contamination in accordance with the National Standards.



Procon Environmental  
[www.pro-enviro.co.za](http://www.pro-enviro.co.za)

We provide Oily Water Separators, Floating Skimmers, Bioremediation and Fuel Filling Overspill Protection.

Call us for further information on our ProSpin innovative hydro cyclone designs, separating oil and other contaminants from water while our Mycelx filtration removes 100% of TPH and oil and grease