




Case Study

<p>Customer</p> <p>Total South Africa Waltloo</p>	<p>Problem</p> <p>Total South Africa need to meet stormwater discharge limits while having low operating and maintenance costs.</p>
<p>Requirement</p> <p>Treatment of oily water wastes from heavy vehicle workshop and vehicle washing. Oil is collected in an above ground tank with automatic drain back to the water collection pit. Depot Effluent Treatment.</p>	<p>Action</p> <p>Procon Environmental installed a 3,5 m³/h system to treat effluent from terminal heavy vehicle workshop and vehicle wash applications.</p>
<p>Year</p> <p>2004</p>	
<p>Discharge Source:</p> <p>Storm water Oil & Grease <50mg/l</p>	
<p>Contact Details</p> <p>Procon Environmental +27 (0)13 697 4617 +27 (0)12 674 9030 procon@pro-enviro.co.za</p>	